



IMPORTANT NOTICE

RECOMMENDED “ VISUAL” INSPECTION OF PAR 1 & 2 - FRYERS

The recommended maintenance inspection type is a simple **VISUAL LOOK**.

Store General manager or manager can do this.

This should be done every **6 MONTHS**. The gaskets are comprised ceramic fibers and are designed to operate in high temperatures. Gaskets will eventually deteriorate. This wear is normal and **DOES NOT** fall under the original warranty policy that pertains to the Ultrafryer. Performing interval **VISUAL** inspections will pro-long your Ultrafryer.

There are a few things to look for when performing a visual inspection.

Firebox

- **check firebox nuts for looseness**
- **check gaskets for any type of deterioration**
- **check for cracks in heat shield replace if crack is over ½ inch long and completely through casting**
- **check firebox cover if missing or just hanging**
- **check ignitor rod, any cracks, burnt**
- **check for carbon build-up**

Blowers

- **check for obstruction to blower**
- **6” clearance between wall and back of fryer**
- **check for carbon build-up on flues**

Controllers

- **check if buttons on computer work (activate a time)**
- **Do lights on computer display light up**

Lights

- **check indicator lights are on**
- **check if broken**

Drain & pump levers

- **check for broken/ missing flap on switches**

The heat shield and gaskets are available through your Ultrafryer regional parts distributor or direct from Ultrafryer along with instructions.

IMPORTANT: The gaskets are specifically engineered for your Ultrafryer and should **NOT** be substituted with other material. Doing so will **VOID** your warranty.

Qualified / Authorized service personnel should perform all repairs.

The following list's the P/N and applicable use:

PAR I FRYERS

Gasket kits

18 & 20 in Vat – P/N 12A166

14 in Vat – P/N 12A162

Replacement heat shield

18 & 20 in Vats - P/N 19A222

14 in Vat – P/N 19A153

PAR II FRYERS

Gasket kits

18 & 20 in Vats – P/N 12A161

14 in Vats – P/N 12A160

Replacement Heat Shields

18 & 20 in Vats – P/N 22A168

14 in Vats – P/N 19A153

For Technical assistance please call 1-800-525-8130